

# Seating Cedar Raised Bed

## Parts Included:

9" long top Corner Triangle Supports- 4  
7" Middle Supports- 2  
Corner Posts-4  
4' Panels- 14  
6' Panels- 14  
Top Seating Panels- 4  
1 1/2" Screws- 46

1. Setup a corner first. Use the 4' panels and slide 7 of the panels down the corner post's notch to create the 4' width span. Note, that all sides come in a set of 7 but the top and bottom panels will have a flat surface. Alternately, use the 6' panels and slide 7 of the panels down to create the adjoining perpendicular corner. Starting from the bottom, screw in a 1 1/2" Philip head screw at each alternate panel. Form the rest of the raised bed as described above



Cedar Panel

2. After setting up the main frame, the top seating panels will complete the top of the raised bed. Using four screws, screw in the top corner support.



Corner Post

Triangle Support

3. The middle support pieces are used to support the middle of the raised bed. Those are screwed in as well.



